

BENDIX/KING KN 63 DME SYSTEM - TROUBLESHOOTING

1. General

- A. This section give the troubleshooting procedures for the Bendix/King KN 63 DME System. For a general overview of the KN 63 system refer to Bendix/King KN 63 DME System - Description and Operation.

2. Bendix/King KN 63 DME System Troubleshooting

- A. Tools and Equipment

NOTE: For the supplier publication part number and manufacturer data, refer to the Introduction - Supplier Publication List.

- (1) Tools and Equipment

- Multimeter.

- (2) Special Consumables

- None.

- (3) Reference Material

- Chapter 23, Garmin GMA 1347/1360D Audio System - Troubleshooting
- Bendix/King KN 63 DME System - Description and Operation
- Bendix/King KN 63 DME System - Adjustment/Test
- Bendix/King KN 63 DME Receiver - Removal/Installation
- Comant DME Antenna - Removal/Installation
- Garmin G1000 Integrated Avionics System - Troubleshooting
- Garmin G1000 Integrated Avionics System - Adjustment/Test
- Model 208 Wiring Diagram Manual.

- B. Do the Bendix/King KN 63 DME System Troubleshooting.

- (1) Refer to Garmin G1000 Integrated Avionics System - Adjustment/Test and do the steps that follow:

- (a) Make sure that the correct software and configuration has been installed.
- (b) Do the Architecture Verification check and make sure all systems are serviceable.

NOTE: The KN 63 DME is not listed on the status page.

- (2) Make sure the GIA2 has check mark (green) and serial number next to its nomenclature on the list.

- (a) This indicates the LRU is serviceable.

NOTE: Serial number is not reported for the following equipment: COM1, COM2, GS1, GS2, GTX1, GTX 2 (OPT), NAV1, NAV2, AND WX500.

- (b) If the GIA2 shows a red X, troubleshoot the GIA. Refer to Garmin G1000 Integrated Avionics System - Troubleshooting.

- (3) Check the primary flight display crew alert system (CAS) window for messages to aid in troubleshooting the anomaly.

- (4) For CAS messages related to other Garmin LRU's, refer to the applicable LRU section for CAS message troubleshooting.

- (5) Push the rightmost softkey on the PFD and make sure that no messages show in the Alerts window.

- (6) Carefully examine the electrical wiring and components as follows:

- (a) Do a visual check of the KN 63 DME receiver electrical connectors and coaxial connector for broken, bent pins and pushed back pins. Refer to the Model 208 Wiring Diagram Manual.

- 1 If necessary, repair the damage.

- (b) If a red X shows on the PFD DME window, make sure that electrical power and ground signals are present at the DME KN 63 receiver.

- 1 At the KN 63 DME receiver electrical connector (PF800) pins 2 and 3 do a check for 28Vdc electrical power.

- 2 At the KN 63 DME receiver electrical connector (PF800) pins A and 1 do a check for airplane ground.

- 3 If necessary, repair or replace the wiring bundles. Refer to the Model 208 Wiring Diagram Manual.

- (c) Make sure that data bus lines are correctly terminated and secure.

CAUTION: Do not touch bus wiring to each other or to shield grounds. Damage to equipment or circuits can result.

- (d) Remove electrical power from the airplane.
 - (e) Use a multimeter to do a continuity check of the data bus wires between the KN 63 DME receiver electrical connector (PF800) pins 6, F, and D, and the GIA 63W/64W No.2 electrical connector (PI512) pins 59, 60 and 62, respectively.
 - 1 Make sure that there is continuity only from each wires related pin end to end and to no other wires, airplanes grounds, or shields.
 - (f) Do a visual check of the wiring components and make sure that all applicable strapping is correct and any necessary G1000 system strapping is correct.
 - (g) Do a visual check of the wiring bundles for damage.
 - 1 If necessary, repair or replace the wiring bundles. Refer to the Model 208 Wiring Diagram Manual.
 - (h) Do a visual check of the coaxial cable connections to the Comant DME antenna.
 - 1 Tighten loose coaxial cable connectors as necessary.
 - 2 Repair or replace unserviceable coaxial cable as necessary.
 - (7) If the KN 63 DME system wiring is serviceable replace the components that follow:
 - (a) Replace the KN 63 DME receiver. Refer to Bendix/King KN 63 DME Receiver - Removal/Installation.
 - 1 Do an operational check of the KN 63 DME system again. Refer to Bendix/King KN 63 DME System - Adjustment/Test.
 - (b) Replace the DME antenna. Refer to Comant DME Antenna - Removal/Installation.
 - 1 Do an operational check of the KN 63 DME system again. Refer to Bendix/King KN 63 DME System - Adjustment/Test.
 - (8) If there is a DME audio problem, do a continuity check between the KN 63 DME receiver electrical connector (PF800) pins 10 and H and GMA audio panel electrical connector (PI501) pins C and N, respectively.
 - (9) If necessary, repair or replace the wiring bundles. Refer to the Model 208 Wiring Diagram Manual.
 - (10) If the DME system wiring is serviceable, troubleshoot the GMA 1347/1360D audio system. Refer to Chapter 23, Garmin GMA 1347/1360D Audio System - Troubleshooting.
- C. Put the Airplane Back to its Initial Condition.
- (1) None.