

**BENDIX/KING KTA-870 TRAFFIC ADVISORY SYSTEM - TROUBLESHOOTING****1. General**

- A. This section gives the troubleshooting procedures for the Bendix/King KTA-870 Traffic Advisory System (TAS). For an overview of the KTA-870 system refer to Bendix/King KTA-870 Traffic Advisory System - Description and Operation.

**2. Bendix/King KTA-870 System Troubleshooting**

- A. Tools and Equipment

**NOTE:** For the supplier publication part number and manufacturer data, refer to the Introduction - Supplier Publication List.

- (1) Tools and Equipment

- Multimeter.

- (2) Special Consumables

- None.

- (3) Reference Material

- Chapter 23, Garmin GMA 1347 Audio System - Troubleshooting
- Bendix/King KTA-870 Traffic Advisory System - Description and Operation
- Bendix/King KTA-870 Traffic Advisory System - Adjustment/Test
- Bendix/King KTA-810 TAS Processor - Removal/Installation
- Bendix/King KCM-805 TAS Configuration Module - Removal/Installation
- Bendix/King KCM-805 TAS Configuration Module - Adjustment/Test
- Bendix/King KTA-870 TAS Antennas - Removal/Installation
- Garmin G1000 Integrated Avionics System - Troubleshooting
- Garmin G1000 Integrated Avionics System - Adjustment/Test
- Model 208 Wiring Diagram Manual.

- B. Do the Bendix/King KTA-870 System Troubleshooting.

- (1) Refer to Do the Architecture Verification check and make sure all related systems are serviceable. Refer to G1000 Integrated Avionics System - Adjustment/Test, G1000 Architecture Verification Check.

- (a) Make sure that the correct software and configuration has been installed.

**NOTE:** The KTA-810 is not listed on the status page.

- (2) Make sure the GIA2 has check mark (green) and serial number next to its nomenclature on the list.

- (a) This indicates the LRU is serviceable.

**NOTE:** Serial number is not reported for the following equipment: COM1, COM2, GS1, GS2, GTX1, GTX 2 (OPT), NAV1, NAV2, AND WX500.

**NOTE:** The components that follow are not listed on the System Status List page: KR 87 ADF, KN 63 DME, KTA 870 TAS, KRA 405B, KHF 1050 HR Radio System, ME406 ELT, and the C406-N ELT.

- (b) If the GIA2 shows a red X, troubleshoot the GIA. Refer to Garmin G1000 Integrated Avionics System - Troubleshooting.

- (3) Check the primary flight display crew alert system (CAS) window for messages to aid in troubleshooting the anomaly.

- (4) For CAS messages related to other Garmin LRU's, refer to the applicable LRU section for CAS message troubleshooting.

- (5) Push the rightmost softkey on the PFD and make sure that no error messages show in the Alerts window.

- (6) Make sure that the KTA-810 processor is configured correctly. Refer to Bendix/King KCM-805 TAS Configuration Module - Adjustment/Test.

- (a) If the configuration module does not configure correctly replace it. Refer to Bendix/King KCM-805 TAS Configuration Module - Removal/Installation.

- (7) Refer to the Model 208 Wiring Diagram Manual and carefully examine the electrical wiring and components as follows:

- (a) Do a visual check of the KTA-810 processor electrical connectors and coaxial connector bent pins and pushed

back pins.

- 1 If necessary, repair the damage.
- (b) If NO DATA shows on the traffic map, make sure that electrical power and ground signals are present at the KTA-810 processor.
  - 1 Remove electrical power from the airplane.
  - 2 At the KTA-810 processor electrical connector (PT700) pins 59 and 82 do a check for 28Vdc electrical power at each pin.
  - 3 At the KTA-810 processor electrical connector (PT700) pins 1, 127 and 128, do a check for airplane ground at each pin.
  - 4 If necessary, repair or replace the wiring bundles. Refer to the Model 208 Wiring Diagram Manual.
- (c) Make sure that data bus lines are correctly terminated and secure.

**CAUTION: Do not touch bus wiring to each other or to shield grounds. Damage to equipment or circuits can result.**

- (d) Use a multimeter to do a continuity check of the data bus wires between the KTA-810 processor receiver electrical connector (PT700) and the 63W GIA No.2 electrical connector (PI512) as given in Table 101.

**Table 101. Continuity Check Table**

<b>ELECTRICAL CONNECTOR (PT700)</b>	<b>63W GIA No.2 ELECTRICAL CONNECTOR (PI502) PINS:</b>
Pin 60	Pin 71
Pin 61	Pin 70
Pin 62	Pin 75
Pin 63	Pin 74
Pin 54	Pin 10
Pin 55	Pin 11

- 1 Make sure that there is continuity only from each wires' related pin end to end and to no other wires, airplanes grounds, or shields.
- (e) Do a visual check of the wiring components and make sure that all applicable strapping is correct and any necessary G1000 system strapping is correct.
- (f) Do a visual check of the wiring bundles for damage.
  - 1 If necessary, repair or replace the wiring bundles. Refer to the Model 208 Wiring Diagram Manual.
- (g) Do a visual check of the coaxial cable connections to the KA-815 directional antenna and the L-Band antenna.
  - 1 Tighten loose coaxial cable connectors as necessary.
  - 2 Repair or replace unserviceable coaxial cable as necessary.
- (8) If the KTA-870 system wiring is serviceable replace the components that follow:
  - (a) Replace the KTA-810 processor. Refer to Bendix/King KTA-810 TAS Processor - Removal/Installation.
    - 1 Do an operational check of the KTA-870 system again. Refer to Garmin G1000 Integrated Avionics System - Adjustment/Test.
  - (b) Replace the KA-815 directional antenna. Refer to Bendix/King KTA-870 TAS Antennas - Removal/Installation.
    - 1 Do an operational check of the KTA-870 system again. Refer to Garmin G1000 Integrated Avionics System - Adjustment/Test.
  - (c) Replace the L-Band antenna. Refer to Bendix/King KTA-870 TAS Antennas - Removal/Installation.
    - 1 Do an operational check of the KTA-870 system again. Refer to Garmin G1000 Integrated Avionics System - Adjustment/Test.
- (9) If there is a KTA-870 system audio problem, do a continuity check between the KTA-810 processor electrical connector (PT700) pins 20 and 21 and GMA audio panel electrical connector (PI501) pins 19 and 39, respectively.
  - (a) If necessary, repair or replace the wiring bundles. Refer to the Model 208 Wiring Diagram Manual.

(b) If the KTA-870 system wiring is serviceable troubleshoot the Garmin GMA 1347 audio system. Refer to Chapter 23, Garmin GMA 1347 Audio System - Troubleshooting.

C. Put the Airplane Back to its Initial Condition.

(1) None.