

## INSPECTION PROGRAM CHANGE SUMMARY

### 1. General

- A. This section gives a list of changes that were made to the inspection program during Revision 33 of this manual. This list gives operators and maintenance personnel a record of the changes to the inspection program and is for reference only.

### 2. Changes

- A. Changes made to the Chapter 5 documents:

(1) 5-10-01 - INSPECTION TIME LIMITS

(a) Added the Elevator Bellcrank Lubrication (Item Code C273030) to Inspection Document 9.

(2) 5-15-09 - INSPECTION DOCUMENT 9

(a) Added Item Code C273030 for the Elevator Bellcrank Lubrication.

- B. Changes to Tasks

(1) The list that follows contains tasks that were revised or added in this revision.

Task Number	Task Title	Action
12-21-02-640	Elevator Bell Crank Lubrication	ADDED