

PROPELLER RPM INDICATOR - TROUBLESHOOTING (PT6A-114/PT6A-114A)

1. General

- A. This section gives a troubleshooting chart to aid the maintenance technician in Propeller RPM Indicator system troubleshooting. This section is applicable for airplanes that do not have the Garmin G1000 system installed, and have the (PT6A-114/PT6A-114A) engine installed. Refer to Figure 101.

Figure 101 : Sheet 1 : Propeller RPM Indicator Troubleshooting Chart

