TRUE AIRSPEED INDICATOR - TROUBLESHOOTING

1. General

A. A troubleshooting chart has been provided to aid the maintenance technician in system troubleshooting. Refer to Figure 101.

Print Date: Mon May 13 08:50:16 CDT 2024




Figure 101: Sheet 1: Airspeed Indicator Troubleshooting Chart

Print Date: Mon May 13 08:50:16 CDT 2024

A14131 POINTER FAILS TO POINTER VIBRATES **RESPOND** CHECK FOR LOOSE MOUNTING SCREWS. IF -PITOT PRESSURE CONNECTION IS NOT PROPERLY CONNECTED TO PRESSURE LINE FROM PITOT OK, CHECK TUBING FOR NOT OK, TIGHTEN TUBE. REPAIR OR REPLACE **EXCESSIVE VIBRATION** SCREWS. DAMAGED LINE AND TIGHTEN AND REPLACE TUBING CONNECTIONS. WITH FLEXIBLE HOSE.

Figure 101: Sheet 2: Airspeed Indicator Troubleshooting Chart

Print Date: Mon May 13 08:50:16 CDT 2024