

SERVICE DOCUMENT LIST**Table 1. Service Bulletin List**

Service Bulletin Number	Title	Service Kit Number	Service Kit Date	Manual Incorporation
CAB85-1	Pilot's Operating Handbook and Checklist Revision	None	7/5/85	No Effect
CAB85-2	Pilot and Copilot Seat Locking Pin Inspection/Modification	SK208-2	8/9/85	3/1/99
CAB85-3	Pilot's Operating Handbook and Checklist Revisions	None	8/9/85	No Effect
CAB85-4	Brake Line Rerouting Improvement	None	8/16/85	No Effect
CAB85-5	Passenger Seat Belt Attach Bolt Improvement	None	8/16/85	No Effect
CAB85-6	Engine Oil Breather Line Improvement	SK208-1	9/13/85	No Effect
CAB85-7	Wing Fuel Tank Vent Line Inspection	None	10/4/85	No Effect
CAB85-8	Engine Left Hand Igniter Harness Rerouting	None	10/18/85	No Effect
CAB85-9	Fuel Quantity Indicating System Improvements	SK208-8	11/1/85	No Effect
CAB85-10	Pitot/Static Tube Inspection	None	11/8/85	No Effect
CAB85-11	Volt/Ammeter Switch Replacement	SK208-3	11/8/85	No Effect
CAB85-12	Circuit Breaker Panel Connector - Jackscrew Replacement	SK208-6	11/8/85	No Effect
CAB85-13	Maximum Takeoff Weight Increase Modification	SK208-12	11/15/85	3/1/99
CAB85-13	Extended Vertical Tail Installation	SK208-13	11/15/85	3/1/99
CAB85-13	Fin/Rudder Hinge Bracket	SK208-14	11/15/85	3/1/99
CAB85-14	Inertial Separator Support Bracket Replacement	SK208-7	12/6/85	No Effect
CAB85-15	Fuel Selector Warning Placard/Revised Emergency Procedure	None	11/27/85	No Effect
CAB85-16	Torque Indicator Installation Improvement	SK208-16	12/13/85	3/1/99
CAB85-17	Flight Hour Recorder System Modification	SK208-9	12/20/85	3/1/99
CAB85-18	Improved Upper Passenger/Cargo Door Gas Spring	None	12/20/85	No Effect
CAB86-1	Overhead Console Light Filter Removal	None	3/28/86	No Effect
CAB86-2	Altimeter Inspection and Modification	None	3/19/86	No Effect
CAB86-3	Fuel Shut-off Valve Screw Replacement	SK208-18	4/11/86	No Effect
CAB86-4	Pilot's Operating Handbook and Checklist Revision	None	4/18/86	No Effect
CAB86-5	Pilot's Operating Handbook and Checklist Revision	None	4/18/86	No Effect
CAB86-6	Pilot's Operating Handbook and Checklist Revision	None	4/18/86	No Effect
CAB86-7	Airspeed Warning Switch Seal Inspection	None	4/18/86	No Effect
CAB86-8	Fuel Selector Off Warning System Installation	SK208-20	10/10/86	6/1/16
CAB86-9	Tire Pressure Placard Replacement	None	4/25/86	No Effect
CAB86-10	Cowl Door Latch Modification	SK208-19	4/25/86	3/1/99
CAB86-11	Improved Lower Passenger Door Gas Spring	None	5/9/86	No Effect
CAB86-12	Inertial Separator Forward and Aft Vane Rivet Inspection	None	4/8/88	No Effect
CAB86-13	Quadrant Cover Replacement	None	6/13/86	No Effect

CAB86-14	Pilot's Operating Handbook Revision	None	5/30/86	No Effect
CAB86-15	Pilot's Operating Handbook Revision	None	6/27/86	No Effect
CAB86-16	Pilot's Operating Handbook and Checklist Revision	None	6/27/86	No Effect
CAB86-17	Sperry Autopilot Roll and Pitch Actuators Modification	None	6/27/86	No Effect
CAB86-18	Improved Drive For Standby Alternator	SK208-17C	12/7/90	3/1/99
CAB86-19	Special Seat Locked and Fuel Contamination Warning Placards	None	7/11/86	No Effect
CAB86-20	Engine Breather Hose Replacement	None	7/18/86	No Effect
CAB86-21	Electrical Bonding Ground Strap Installation	SK208-11	7/25/86	3/1/99
CAB86-22	Pilot's Operating Handbook Revision	None	8/15/86	No Effect
CAB86-23	Passenger Seat Track Fitting Inspection/Replacement	None	8/22/86	No Effect
CAB86-24	External Start Contactor Suppressor	SK208-24	8/29/86	3/1/99
CAB86-25	Fuselage Sealing Procedures	SK208-27	9/5/86	No Effect
CAB86-26	Low Fuel Level Transmitter Nut Retention	SK208-26A	9/5/86	No Effect
CAB86-27	Water Drainage Improvement - Cargo Pod Equipped Airplanes	SK208-10D	6/19/87	3/1/99
CAB86-28	Pilot's Operating Handbook Revisions	None	9/26/86	No Effect
CAB86-29	Pilot's Operating Handbook Revision	None	10/10/86	No Effect
CAB86-30	Pilot's Operating Handbook Revision	None	10/10/86	No Effect
CAB86-31	Pilot's Operating Handbook Revision	None	10/10/86	No Effect
CAB86-32	Improved Secondary Exhaust System	SK208-23E	12/21/90	3/1/99
CAB86-33	King KWX56 Radar Antenna Moisture Control Improvement	None	11/07/86	No Effect
CAB87-1	Cabin Door Lock Improvements	None	1/23/87	No Effect
CAB87-2	Pilot's Checklist Revision	None	3/6/87	No Effect
CAB87-3	Pilot's Checklist Revision	None	3/6/87	No Effect
CAB87-4	Pilot's Checklist Revision	None	3/6/87	No Effect
CAB87-5	Windshield Anti-Ice System Improvement	SK208-39	4/24/87	3/1/99
CAB87-6	Flap Actuator Support Inspection and Replacement	None	5/8/87	No Effect
CAB87-7	Seat Belt Replacement-Stowable Seats	None	5/8/87	No Effect
CAB87-8	Modification of Cargo Door Removed Kit	None	5/8/87	No Effect
CAB87-10	Pilot's Operating Handbook and Checklist Revision	None	7/24/87	No Effect
CAB87-11	Cargo Door Deflector Kit Installation	AK208-2	7/31/87	8/1/95
CAB87-12	Engine Inertial Separator Assembly Improvements	SK208-22 SK208-35	9/18/87	No Effect
CAB87-13	Fuel Reservoir and Flapper Valve Modification	SK208-25	10/16/87	3/1/99
CAB87-14	Fuel Reservoir Tank/Wing Bay Primer Adhesion Inspection	None	10/16/87	No Effect
CAB87-15	Circuit Breaker Inspection/Replacement	None	11/17/87	No Effect
CAB87-17	Large Oil Cooler Installation	SK208-40	12/18/87	3/1/99

CAB87-18	Floorboard Cover Material Removal/Access Cover Replacement	None	12/18/87	No Effect
CAB87-19	Pilot's Operating Handbook and Checklist Revision	None	12/18/87	No Effect
CAB87-20	Engine Oil Scavenge Pump Retaining Nut Lockwasher Replacement	None	12/29/87	No Effect
CAB88-2	Nose/Main Landing Gear Wheel and Bearing improvements	SK208-21	3/4/88	No Effect
CAB88-3	Pilot's Operating Handbook Revision	None	3/18/88	No Effect
CAB88-4	Pilot's Operating Handbook and Checklist Revision	None	3/18/88	No Effect
CAB88-5	Control Column Aileron Cable Guard Improvement	SK208-30	3/18/88	No Effect
CAB88-6	Outboard Wing Fuel Drain Valve Installation	SK208-36	3/18/88	3/1/99
CAB88-7	Elevator Trim Chain Cover Installation	SK208-38	3/18/88	No Effect
CAB88-8	Radio Cover Watershield Installation and Cabin Top Sealing Inspection	SK208-42	3/18/88	3/1/99
CAB88-9	Tow Limit Modification	SK208-48	3/18/88	3/1/99
CAB88-10	Improved Fuel Flow Transducer Electrical Connector	None	3/25/88	No Effect
CAB88-11	Bleed Air Valve Pressure Regulator Poppet Nut Inspection and Modification	None	3/25/88	No Effect
CAB88-12	Main Landing Gear Lower Fairing Improvement	None	11/11/88	No Effect
CAB88-13	Flap System Adjustable Interconnect Rod Installation	SK208-50	3/25/88	No Effect
CAB88-14	Shimmy Dampener Improvement	None	4/8/88	No Effect
CAB88-15	Inertial Vane Separator Vane Improvements	SK208-45B	4/8/88	3/1/99
CAB88-16	Improved Door Restraint Installation	SK208-29	4/15/88	3/1/99
CAB88-17	Cowl Door Rub Strip Improvement	SK208-47	4/22/88	No Effect
CAB88-18	Cargo Barrier Attachment Improvement	SK208-37	5/6/88	3/1/99
CAB88-20	Exhaust Hanger Modification (Cargo Pod or Floats)	SK208-55	5/31/88	3/1/99
CAB88-22	Reduced Rudder Travel Limits	None	1/13/89	No Effect
CAB88-23	Wing Fuel Tank External Sump Installation	SK208-52	7/29/88	3/1/99
CAB88-25	Partition Net Placard Installation	SK208-46	7/29/88	3/1/99
CAB88-26	Circuit Breaker Panel Cover Installation	SK208-32 SK208-33 SK208-34	7/29/88	3/1/99
CAB88-27	Elevator Balance Inspection	None	8/19/88	No Effect
CAB88-29	Pilot's Operating Handbook Revision	None	9/23/88	No Effect
CAB88-30	Pilot's Operating Handbook Revision	None	9/23/88	No Effect
CAB88-31	Pilot's Operating Handbook and Checklist Revision	None	9/23/88	No Effect
CAB88-32	Wing Skin Stiffener Installation	SK208-63	10/14/88	No Effect
CAB88-33	Oxygen Gage Line Rerouting	None	10/28/88	No Effect
CAB88-34	Static Source Selector Valve Modification	SK208-54	11/11/88	No Effect
CAB88-36	Pitot Static System Line Replacement	SK208-49	11/18/88	3/1/99
CAB88-37	ELT Switch Placard Replacement	None	12/9/88	No Effect

CAB88-38	Flashing Beacon Circuit Breaker Inspection/Replacement	None	12/9/88	No Effect
CAB88-39	Pilot/Copilot Seat Four Point Restraint Harness Installation	None	12/9/88	No Effect
CAB88-40	Nose Gear Steering Bushing Replacement	SK208-59	12/9/88	No Effect
CAB88-41	Cowl Scupper and Drain Installation	SK208-43	12/9/88	3/1/99
CAB89-1	Engine Oil Hose Replacement	SK208-61	1/6/89	3/1/99
CAB89-2	Nose Gear Torque Link Replacement	SK208-51D	7/6/90	3/1/99
CAB89-3	Door Lock Pin Replacement	SK208-62	1/13/89	No Effect
CAB89-4	Pointer 3000-1 ELT Installation	SK208-58	11/2/98	Superseded by CAB97-7
CAB89-6	Fuel Control Manual Override Arm Bushing Installation	None	2/10/89	6/1/16
CAB89-7	Vacuum Exhaust Ejector Fitting Improvement	None	2/17/89	No Effect
CAB89-8	Main Gear Upper Elbow Fairing Installation	None	2/17/89	No Effect
CAB89-9	Avionics Cover Plate Modification	None	3/31/89	No Effect
CAB89-10	Propeller Overspeed Governor Improvement	None	2/18/94	No Effect
CAB89-11	Utility Seat Frame Padding Installation	SK208-60	5/19/89	No Effect
CAB89-12	Control Cable Special Inspection	None	5/19/89	No Effect
CAB89-13	Landing Gear Wheel Bearings Special Inspection and Lubrication	None	5/19/89	No Effect
CAB89-14	Crew Step Attach Area Structural Improvements	SK208-41 SK208-44	6/2/89	3/1/99
CAB89-15	Wing Strut Cuff Fairing Anti-Chafe Methods	None	6/2/89	No Effect
CAB89-16	Fuel Pump Drain Reservoir Installation	SK208-57	6/9/89	6/1/16
CAB89-17	Pilot's Operating Handbook Revision	None	6/16/89	No Effect
CAB89-18	Cargo Pod Door Latch Modification	None	6/30/89	No Effect
CAB89-19	Air Conditioner Compressor Bracket Replacement	SK208-66	7/14/89	3/1/99
CAB89-20	Inertial Separator Drain Installation	None	7/14/89	No Effect
CAB89-21	Fuel System Roll Pin Safetying	None	11/17/89	6/1/11
CAB89-22	Pilot's Operating Handbook and Checklist Revision	None	8/11/89	No Effect
CAB89-23	Lead-Acid Battery Tie Down Strap Improvement	None	8/25/89	3/1/99
CAB89-25	Elevator Control Link Replacement	None	12/14/90	No Effect
CAB89-26	Bleed Air Pressure Relief Valve Installation	SK208-64 SK208-65	6/15/90	Superseded by CAB90-14
CAB89-27	Standby Alternator Drive Pulley Inspection/Replacement	None	9/22/89	No Effect
CAB89-29	Power Relay Box Connector Sealing	None	10/6/89	No Effect
CAB89-30	Enlarged Cargo Pod Heat Shield Installation	SK208-69	11/3/89	6/1/11
CAB89-31	Inboard Flap Roller and Track Removal	SK208-71	11/24/89	3/1/99
CAB89-32	Upper Right Flap Bellcrank Support Replacement	SK208-72A	6/30/95	Superseded by CAB95-11

CAB89-33	Engine Fuel Nozzle Inspection - Cancelled and Superseded by Pratt & Whitney Maintenance Manuals P/N 3021242 and 3030442	None	3/12/93	No Effect
CAB89-34	Flap Bellcrank Weld Inspection	None	12/22/89	No Effect
CAB90-1	Pilot's Operating Handbook and Checklist Revisions	None	1/19/90	No Effect
CAB90-2	Inspection and Lubrication of Engine Fuel Control Rod Ends and Linkage	None	3/12/93	3/1/08
CAB90-4	Generator Field Circuit Breaker Inspection and Screw Replacement	None	2/23/90	No Effect
CAB90-5	Nose Gear Fork Tow Point	SK208-74	3/2/90	3/1/99
CAB90-6	Circuit Breaker Inspection/Replacement - Flap Circuit	None	3/9/90	No Effect
CAB90-7	Engine Mount Bracket Drainage and Bolt	None	6/1/90	6/1/16
CAB90-8	Large Engine Oil Cooler Hose Replacement	None	3/23/90	No Effect
CAB90-9	Airborne Bleed Air Valves Retrofit Kit	SK208-70	6/15/90	3/1/99
CAB90-10	Cargo Loading Manual Revision	None	3/23/90	No Effect
CAB90-12	Landing Gear Springs Paint Adhesion Inspection and Repair	None	6/22/90	No Effect
CAB90-14	Bleed Air Pressure Relief Valve Removal	None	3/12/93	3/1/99
CAB90-15	Pitot Static System Flareless Fitting Inspection	None	4/27/90	No Effect
CAB90-16	Crew Door Sill to Bulkhead Flange Gap Inspection	None	5/4/90	No Effect
CAB90-17	Pilot's Operating Handbook Revision	None	6/1/90	No Effect
CAB90-18	Pilot's Operating Handbook Revision	None	6/22/90	No Effect
CAB90-19	Engine Oil Filler Cap Security	None	6/22/90	No Effect
CAB90-20	McCauley Propeller Installation	None	12/21/90	12/1/06
CAB90-21	Bulkhead Control Cable Cutout Modification	SK208-75B SK208-76B	6/21/91	No Effect
CAB90-24	Engine Fuel Control Actuating Lever Improvement	None	8/24/90	No Effect
CAB90-25	Fire Detect Sensor Clamp Installation	None	9/7/90	No Effect
CAB90-26	Main Landing Gear Brake Line Replacement	None	10/12/90	No Effect
CAB90-27	Secondary Exhaust Duct Mid Support Removal	None	10/26/90	11/3/03
CAB90-28	Pilot's Operating Handbook and Checklist Revisions	None	11/2/90	No Effect
CAB90-30	Pilot's Operating Handbook and Checklist Revisions	None	11/2/90	No Effect
CAB90-31	Flap Bellcrank Weld Inspection	None	11/16/90	No Effect
CAB90-32	Improved Airspeed Warning Switch Installation	SK208-79	12/7/90	3/1/98
CAB90-33	Pilot's Operating Handbook, Checklist and Cargo Loading Manual Revision	None	12/21/90	No Effect
CAB90-34	Engine Oil Filler Cap Security Warning Placard Installation	None	12/21/90	No Effect
CAB91-1	Engine Oil Filler Tube Modification	None	1/25/91	No Effect
CAB91-2	Outboard Flap Pushrod Bolt and Cable Inspection	None	2/22/91	No Effect
CAB91-3	Cargo Pod Door Latch Modification	None	3/8/91	No Effect
CAB91-4	Main Landing Gear Rubber Fairing Modification	None	3/22/91	No Effect

CAB91-5	Pilot's Operating Handbook and Checklist Revisions	None	3/22/91	No Effect
CAB91-6	Pilot's Operating Handbook and Checklist Revisions	None	3/22/91	No Effect
CAB91-7	Pilot's Operating Handbook and Checklist Revisions	None	3/22/91	No Effect
CAB91-8	Pilot's Operating Handbook and Checklist Revisions	None	3/22/91	No Effect
CAB91-9	Firewall Fitting Reinforcement Installation	SK208-90	7/2/92	3/1/98
CAB91-10	Bench Seat Belt and Harness Retention	None	4/19/91	----
CAB91-11	Bleed Air Pressure Regulator Discharge Pressure Check	None	3/12/93	Cancelled
CAB91-12	Air Conditioner Condenser Cowl Seal Replacement	SK208-78	4/26/91	3/1/98
CAB91-13	Hartzell Propeller Blade Inspection	None	3/20/92	No Effect
CAB91-18	Pilot's Operating Handbook and Checklist Revisions	None	6/28/91	No Effect
CAB91-19	Pilot's Operating Handbook Revision	None	6/28/91	No Effect
CAB91-20	Pilot's Operating Handbook and Checklist Revisions	None	6/28/91	No Effect
CAB91-21	Pilot's Operating Handbook and Checklist Revisions	None	6/28/91	No Effect
CAB91-22	Engine Fuel Control Lever Replacement	SK208-95	7/5/91	3/1/98
CAB91-24	Door Handle Plunger Replacement	SK208-81	8/2/91	No Effect
CAB91-25	Air Conditioner Compressor Drive Assembly End Cap Replacement	None	8/16/91	No Effect
CAB91-26	Heater Valve Improvement	SK208-82	8/30/91	3/1/98
CAB91-27	Control Column Bearings and Aileron Cable Guard Replacements	SK208-83	9/20/91	3/1/98
CAB91-29	Nose Gear to Cargo Pod Fairing Modification	None	10/11/91	No Effect
CAB91-30	Nose Gear Axle Spacer Replacement	None	10/11/91	5/1/96
CAB91-32	Engine Chip Detector Inspection and Replacement	None	11/1/91	No Effect
CAB91-33	Radome Sealing Procedures	None	11/15/91	5/1/14
CAB91-34	Engine Power Control Cable Replacement	SK208-94	11/22/91	3/1/98
CAB91-35	Microphone Switch Diode Installation	None	12/13/91	No Effect
CAB92-1	Generator Control Unit Modification	None	1/17/92	No Effect
CAB92-2	Upper Rudder Hinge Bracket/Skin Reinforcement	SK208-88	1/17/92	3/1/98
CAB92-3	Lucas Starter/Generator Brush Inspection	None	1/24/92	No Effect
CAB92-4	Forward Fuselage Side Vent Installation Sealing	None	2/14/92	No Effect
CAB92-5	Hartzell Propeller Installation	None	4/10/92	No Effect
CAB92-6	Pilot's Operating Handbook and Checklist Revisions	None	4/24/92	No Effect
CAB92-7	Pilot's Operating Handbook and Checklist Revisions	None	4/24/92	No Effect
CAB92-8	Pilot's Operating Handbook and Checklist Revisions Mandatory	None	4/24/92	No Effect
CAB92-9	Pilot's Operating Handbook and Checklist Revisions	None	4/24/92	No Effect
CAB92-11	Pilot's Operating Handbook Revision	None	5/22/92	No Effect
CAB92-12	Pilot's Operating Handbook Revision	None	5/22/92	No Effect
CAB92-13	Pilot's Operating Handbook Revision	None	5/22/92	No Effect

CAB92-14	PT6A-114/-114A Engine Compressor Turbine Blade Inspection	None	12/31/92	No Effect
CAB92-15	Flap Bellcrank Connecting Rod Clearance Inspection and Modification	SK208-98	7/24/92	No Effect
CAB92-16	Flap Support Inspection and Modification	SK208-92D	4/30/93	No Effect
CAB92-17	Left Fuselage Sidewall Electrical Connectors Relocation	None	9/11/92	No Effect
CAB92-18	Rudder Torque Tube Inspection and Rudder Hinge Replacement	SK208-99D	4/30/93	3/1/98
CAB92-19	Low Fuel Level Switch Cover Replacement	SK208-110	10/23/92	3/1/99
CAB92-20	Pilot's Operating Handbook and Checklist Revisions	None	10/23/92	No Effect
CAB92-21	Pilot's Operating Handbook and Checklist Revisions	None	10/23/92	No Effect
CAB92-22	Pilot's Operating Handbook and Checklist Revisions	None	10/23/92	No Effect
CAB92-24	Airspeed Limitation Placard Installation	None	11/13/92	No Effect
CAB93-1	Airborne Bleed Air Control Components Improvements	None	1/29/93	No Effect
CAB93-2	Bleed Air System Pressure Relief Valve Installation	SK208-112	3/12/93	3/1/99
CAB93-3	Cabin Floorboard Reinforcement Installation	SK208-97 SK208-103	4/30/93	No Effect
CAB93-4	Propeller Control Cable Replacement	SK208-108	4/30/93	3/1/99
CAB93-5	Crew Door Upper and Lower Hinge Attach Repair	SK208-101	4/30/93	3/1/99
CAB93-6	Rudder Upper and Center Hinge Replacement	SK208-104A SK208-105A	5/28/93	3/1/99
CAB93-9	Throttle Control Quadrant Cover Doubler Installation	SK208-111A	7/23/93	3/1/99
CAB93-10	Pilot's Operating Handbook Revision	None	7/23/93	3/1/99
CAB93-11	Flap Outboard Support Inspection and Modification	SK208-109	8/27/93	No Effect
CAB93-12	Elevator Hinge Replacement	SK208-102 SK208-106 SK208-107	8/27/93	3/1/99
CAB93-13	Aileron Cable Seal Retainer Inspection	None	8/27/93	No Effect
CAB93-14	Flap Bellcrank Safe Life Limit	None	8/27/93	3/1/99
CAB93-16	Battery Box Latch Pivot Bolt Reversal	None	9/17/93	No Effect
CAB93-17	Pilot's Operating Handbook Revision	None	9/24/93	No Effect
CAB93-18	Aileron Outboard Hinge Bolt Inspection/Replacement	SK208-116	10/8/93	3/1/08
CAB93-19	Oxygen Control Lever Modification	SK208-115A	10/22/93	8/1/95
CAB93-20	Cargo Pod and Landing Gear Fairing De-Ice System Installation	AK208-6F	10/22/93	---
CAB93-21	Windshield Anti-Ice Panel Upper Retention Modification	SK208-113	11/19/93	8/1/95
CAB93-22	Flap Support Roller Washer Installation	None	11/19/93	6/1/16
CAB94-1	Pilot's Operating Handbook and Checklist Revisions	None	1/21/94	No Effect
CAB94-2	Pilot's Operating Handbook and Checklist Revisions	None	1/21/94	No Effect

CAB94-3	Pilot's Operating Handbook and Checklist Revisions	None	2/11/94	No Effect
CAB94-4	Pilot's Operating Handbook and Checklist Revisions	None	2/11/94	No Effect
CAB94-5	Standby Alternator Output Wire Replacement	None	2/11/94	No Effect
CAB94-6	Engine Igniter Inspection	None	2/11/94	No Effect
CAB94-8	Avionics Wire Harness Grounding Connector Inspection	None	2/11/94	No Effect
CAB94-9	Elevator Trim Chain Cover Installation	SK208-118	3/25/94	8/1/95
CAB94-10	Pilot's Checklist Revision	None	2/18/94	No Effect
CAB94-11	Inboard Fuel Filler Installation	AK208-10A	2/18/94	No Effect
CAB94-12	Pilot's Operating Handbook Revision	None	4/29/94	No Effect
CAB94-13	Flap Support and System Inspections and Operational Check	None	7/1/94	No Effect
CAB94-14	Flap Bellcrank Bolt Inspection/Replacement	None	6/30/95	Superseded by CAB95-11
CAB94-15	Right Hand Airspeed Indicator Inspection	None	10/14/94	No Effect
CAB94-16	Flap Switch Guard Installation/Modification	SK208-119	10/28/94	8/1/95
CAB94-17	PT6A-114A Engine Vane Ring Damping Strap	None	8/18/95	No Effect
CAB94-18	Main Landing Gear Fairing Baffle Modification	None	12/30/94	No Effect
CAB95-1	Nose Cap/Induction Inlet Support and Engine Flange Guard Installation	None	2/17/95	8/1/95
CAB95-2	Nose Landing Gear Nut Replacement	None	2/24/95	No Effect
CAB95-3	Pilot's Operating Handbook Revision	None	4/14/95	No Effect
CAB95-4	Pilot's Operating Handbook Revision	None	4/14/95	No Effect
CAB95-5	Pilot's Operating Handbook Revision	None	4/14/95	No Effect
CAB95-6	Crew Seat Vertical Adjust Bearing Inspection/Replacement	SK208-117A	5/26/95	No Effect
CAB95-7	Airplane Flight Manual Supplement Revision	None	6/23/95	No Effect
CAB95-8	Pilot's Operating Handbook and Checklist Revisions	None	6/23/95	No Effect
CAB95-9	Pilot's Operating Handbook and Checklist Revisions	None	6/23/95	No Effect
CAB95-10	Pilot's Operating Handbook and Checklist Revisions	None	6/23/95	No Effect
CAB95-11	Flap Bellcrank Attach Bolt Replacement	SK208-123B	8/18/95	8/1/95
CAB95-12	Parking Brake Valve Inspection/Replacement	None	7/28/95	No Effect
CAB95-13	Nose Landing Gear Spring Inspection and Identification	None	07/28/95	7/18/95
CAB95-14	PT6A-114A Engine Third Stage Compressor Stator Assembly Replacement	None	8/18/95	No Effect
CAB95-15	Pilot's Operating Handbook Revision	None	8/25/95	No Effect
CAB95-16	Pilot's Operating Handbook Revision	None	8/25/95	No Effect
CAB95-17	Pilot's Operating Handbook Revision	None	8/25/95	No Effect
CAB95-18	Auxiliary Fuel Pump Relay Replacement	None	9/8/95	No Effect
CAB95-19	Cargo Pod and Landing Gear Fairing De-Ice System Installation	AK208-6F	10/13/95	No Effect

CAB95-20	Pilot's Operating Handbook Revision	None	11/10/95	No Effect
CAB95-21	Pilot's Operating Handbook Revision	None	11/10/95	No Effect
CAB95-22	Pilot's Operating Handbook Revision	None	11/10/95	No Effect
CAB96-1	Cargo Loading Placard Modification	None	1/26/96	No Effect
CAB96-2	Crew and Cargo Door Hinge Pin Replacement	None	1/26/96	No Effect
CAB96-3	Nose Landing Gear Shimmy Dampener Installation Inspection and Modification	None	1/26/96	No Effect
CAB96-4	Annunciator Panel Transistor Modification	None	8/9/96	No Effect
CAB96-5	Annunciator Panel Placard Installation	None	1/26/96	No Effect
CAB96-6	Pilot's Operating Handbook Revision	None	1/26/96	No Effect
CAB96-7	Pilot's Operating Handbook Revision	None	1/26/96	No Effect
CAB96-8	Pilot's Operating Handbook Revision	None	1/26/96	No Effect
CAB96-9	Engine Oil Filler Placard	None	2/9/96	5/1/96
CAB96-10	Avionics Cooling Fan Replacement	SK208-128	2/9/96	No Effect
CAB96-11	Ignitor Lead Cable Routing Modification	SK208-125	3/1/96	No Effect
CAB96-12	Gyro Installation Vacuum Hose Replacement	None	5/3/96	No Effect
CAB96-13	Airborne Fuel Pump Inspection/Replacement	None	6/21/96	No Effect
CAB96-15	Fuel Hose Inspection/Replacement	None	10/18/96	No Effect
CAB96-16	AN3-5A Bolt Inspection/Replacement	None	7/19/96	No Effect
CAB96-17	Pilot's Operating Handbook and Checklist Revisions	None	8/9/96	No Effect
CAB96-18	Pilot's Operating Handbook and Checklist Revisions	None	8/9/96	No Effect
CAB96-19	Pilot's Operating Handbook and Checklist Revisions	None	8/9/96	No Effect
CAB96-20	Nose Landing Gear Spring Fork Attach Bolt Inspection/Modification	None	9/13/96	3/1/99
CAB96-22	PT6A-114/-114A Engine Bleed Off Valve Cover Inspection/Replacement	None	12/6/96	No Effect
CAB96-23	Standby Alternator Drive Pulley With Drain and Oil Collection Can	SK208-122	12/16/96	5/1/96
CAB96-24	Nose Landing Gear Drag Link Spring Inspection/Modification	None	12/16/96	No Effect
CAB97-1	KLN 89B GPS Navigation System Software	None	6/30/97	No Effect
CAB97-2	Engine Power Control Cable Umbrella Seal Installation	None	2/24/97	No Effect
CAB97-3	Pilot's Operating Handbook and Checklist Revisions	None	3/3/97	No Effect
CAB97-4	Pilot's Operating Handbook and Checklist Revisions	None	3/3/97	No Effect
CAB97-5	Pilot's Operating Handbook and Checklist Revisions	None	3/3/97	No Effect
CAB97-6	Airplane Flight Manual Supplement Revision	None	3/31/97	No Effect
CAB97-7	Pointer 3000-11 ELT Installation	AK208-13	4/28/97	No Effect
CAB97-8	Avionics Number Two Power Switch/Breaker Replacement	SK208-130	6/30/97	No Effect
CAB97-9	KLN 89B GPS Navigation System Approach Restrictions	None	7/2/97	No Effect

CAB97-10	Cowl Door Latch Inspection	None	7/28/97	No Effect
CAB97-11	Electrical Isolation of Pilot and Copilot Press to Talk Switches	SK208-127A	10/27/97	No Effect
CAB97-12	Left Inboard Aft Flap Bellcrank Replacement	None	10/27/97	No Effect
CAB98-1	Pilot's Operating Handbook Revisions	None	1/19/98	No Effect
CAB98-2	Passenger Door Step Support Modification	SK208-133	2/23/98	6/1/16
CAB98-3	Pilot's Checklist Revisions	None	2/23/98	No Effect
CAB98-4	Engine Fuel Manifold Adapter Assembly Inspection	None	6/15/98	No Effect
CAB98-6	Main Landing Gear Lower Fairing Baffle Replacement	SK208-134	3/23/98	No Effect
CAB98-7	Voltage Suppression Jumper Installation	None	4/27/98	No Effect
CAB98-9	Right Brake Master Cylinder Supply Hose Modification	SK208-136	5/4/98	No Effect
CAB98-11	Engine Fuel Manifold Adapter Assembly Inspection	None	6/28/99	No Effect
CAB98-12	KLN 89B GPS Navigation System IFR Non-Precision Approach Limitation	None	7/20/98	No Effect
CAB98-13	ART 2000-6 Weather Radar Modification	None	8/31/98	No Effect
CAB98-14	Radar Pod Drain Hole Modification and Scupper Installation	None	8/31/98	No Effect
CAB98-15	Engine Bleed Off Valve Diaphragm Inspection	None	10/5/98	No Effect
CAB98-17	Fuel Reservoir Structure Modification	SK208-121A	11/30/98	No Effect
CAB98-18	PT6A Engine No. 1 Bearing Outer Housing Inspection	None	11/30/98	No Effect
CAB98-19	Pilot's Operating Handbook and Pilot's Checklist Revisions	None	12/21/98	No Effect
CAB99-1	Engine Bleed Off Valve Cover and Diaphragm Inspection	None	12/27/99	No Effect
CAB99-2	KLN 89B GPS Navigation System Modification	None	6/28/99	No Effect
CAB99-3	Shimmy Dampener Modification	None	6/28/99	No Effect
CAB99-4	Pilot's Operating Handbook and Pilot's Checklist Revisions	None	8/23/99	No Effect
CAB99-5	Emergency Locator Transmitter (ELT) Operational Test	None	10/4/99	No Effect
CAB99-6	Engine Bleed Off Valve Replacement	None	5/29/00	No Effect
CAB99-8	Pilot's Operating Handbook and Pilot's Checklist Revisions	None	11/29/99	No Effect
CAB99-9	Yaw Damper AC Inverter Wiring Fuse Installation	None	11/29/99	No Effect
CAB00-1	Stall Warning Ground Operations Disable Switch Installation	AK208-22	3/6/00	No Effect
CAB00-2	Generator Contactor Transzorb Installation	None	3/6/00	No Effect
CAB00-3	Main Landing Gear Axle Inspection/Replacement	None	3/6/00	3/1/12
CAB00-4	KY 196A VHF COMM Transceiver Modification	None	4/17/00	No Effect

CAB00-5	Rudder Bar Assembly Modification and Barrel Nut Replacement	SK208-140	4/17/00	No Effect
CAB00-7	Engine Fuel Pump Inspection/Replacement	None	4/17/00	No Effect
CAB00-8	Engine Secondary Exhaust Duct Hanger Modification and Cowling Inspection	SK208-129	5/29/00	11/3/03
CAB00-9	Engine Secondary Exhaust Duct Hanger Modification	SK208-139A	7/30/01	11/3/03
CAB00-11	Standby Alternator and Propeller De-Ice Electrical Wiring Modification	None	8/21/00	No Effect
CAB00-12	Pilot and Copilot Seat Rails and Floor Structure Modification	SK208-138	10/30/00	No Effect
CAB00-13	Propeller Anti-Ice Timer Inspection/Replacement	None	11/13/00	No Effect
CAB01-1	Pilot's Operating Handbook and Pilot's Checklist Revisions	None	1/15/01	No Effect
CAB01-2	Vacuum System Air Filter Element Inspection/Replacement	None	1/15/01	No Effect
CAB01-3	KMA24 Audio Panel Wiring Modification	None	1/29/01	No Effect
CAB01-4	Encoding Altimeter Inspection	None	2/12/01	No Effect
CAB01-7	Airplane Hoist Ring Inspection	None	3/26/01	No Effect
CAB01-8	Horizontal and Vertical Stabilizer Attach Bolt Inspection	None	5/7/01	No Effect
CAB01-10	KLN 94 GPS Navigation System Software Upgrade	None	10/8/01	No Effect
CAB01-11	KAS 297B Altitude Preselect Wiring Modification	None	11/5/01	No Effect
CAB01-12	Pilot's Operating Handbook and Pilot's Checklist Revisions	None	12/3/01	No Effect
CAB01-13	Engine Oil Tube Clamp Modification	None	12/3/01	6/1/16
CAB01-14	KFC 225 Automatic Flight Control Computer System Restrictions	None	12/10/01	No Effect
CAB01-15	Emergency Power Lever Shear Wire Installation	SK208-142	12/17/01	12/17/01
CAB01-16	Transcal Altitude Digitizer Wiring Modification	None	12/17/01	No Effect
CAB02-1	Flap System Inboard Forward Bellcrank Life Limit and Inspection	None	1/27/03	11/3/03
CAB02-2	Wing Spar Inspection and Inspection Plate Modification	None	6/16/03	11/3/03
CAB02-3	Plywood Floorboard Installation - 5/8 Inch	SK208-145	2/25/02	11/3/03
CAB02-4	Emergency Power Lever Control Cable Bracket Replacement	None	4/22/02	11/3/03
CAB02-6	Brazilian Airplane Flight Manual and Pilot's Checklist Revisions	None	6/17/02	No Effect
CAB02-7	Concord SLA Replacement Battery Installation	None	8/12/02	6/1/16
CAB02-9	Pilot's Operating Handbook and Pilot's Checklist Revisions	None	6/17/02	No Effect
CAB02-10	KAC 501 Radar and KAC 502 Terrain Module Modification	None	8/12/02	No Effect
CAB02-11	Fuel-Vent Line Float Valves Inspection	None	8/12/02	11/3/03

CAB02-12	Flap System Inboard Forward Bellcrank Installation	SK208-148A	1/27/03	11/3/03
CAB02-13	Engine Mount Bolts and Washers Inspection	None	3/24/03	11/3/03
CAB02-14	Fuel Filter Element Inspection	None	12/9/02	No Effect
CAB03-1	Pilot's Operating Handbook Revision	None	2/14/03	No Effect
CAB03-2	Engine Oil Pressure/Oil Temperature Indicator Installation	SK208-147	2/24/03	No Effect
CAB03-3	Flight Hourmeter Electrical Wiring Modification	None	6/2/03	No Effect
CAB03-4	Honeywell IN 182A-16 and IN 812A-12 Radar Indicator Inspection/Modification	None	5/19/03	No Effect
CAB03-5	Main Landing Gear Brake Line and Deice Line Clamp Replacement	None	12/15/03	No Effect
CAB03-6	Main Landing Gear to Fuselage Fairing Modification and Trunnion Inspection	None	6/16/03	No Effect
CAB03-7	Main Landing Gear Part Number and Serial Identification Placard Installation	None	6/16/03	No Effect
CAB03-8	British Aeroplane Flight Manual Revision	None	6/16/03	No Effect
CAB03-9	Honeywell KS 270C and 272C Servo Friction Inspection	None	6/30/03	No Effect
CAB03-10	Brazilian Airplane Flight Manual and Pilot's Checklist Revision	None	7/28/03	No Effect
CAB03-11	Flap System Bell Cranks Weld Inspection	None	9/24/03	11/3/03
CAB03-12	Honeywell KC 225 Flight Control Computer Modification	None	9/22/03	No Effect
CAB03-13	Rudder Pedal Clevis Inspection/Replacement	None	11/3/03	No Effect
CAB03-14	Argentine Airplane Flight Manual Revisions	None	12/15/03	No Effect
CAB04-1	Fuel Quantity Transmitter Inspection/Replacement	None	2/9/04	No Effect
CAB04-2	Vertical Fin Tip Inspection/Modification	None	2/9/04	No Effect
CAB04-3	Aileron Bell Crank Weld Inspection	None	3/8/04	No Effect
CAB04-4	Engine Primary Exhaust Duct Replacement	None	3/8/04	No Effect
CAB04-5	Security Lock Installation	SK208-159	6/14/04	No Effect
CAB04-6	Pitot Tube Inspection	None	7/26/04	No Effect
CAB04-7	Pilot's Operating Handbook Supplement S1 Revisions	None	8/23/04	No Effect
CAB04-8	Air Conditioner Compressor Drive Inspection	None	6/11/07	No Effect
CAB04-9	Ice Protection Installation/Modification	SK208-146	10/4/04	----
CAB04-10	Honeywell KGP 560 Enhanced Ground Proximity Warning System Modification	None	11/1/04	No Effect
CAB04-11	Honeywell KMH 820 Multi-hazard Sensor Modification	None	11/1/04	No Effect
CAB04-12	Air Conditioning Conversion From R12 to R134A Refrigerant	SK208-156	11/1/04	6/1/16
CAB05-1	Honeywell KLN 94 GPS Navigation System Modification	None	1/24/05	No Effect

CAB05-2	ARTEX Three Frequency Emergency Locator Transmitter (ELT) Installation	SK208-163	1/24/05	No Effect
CAB05-3	Torque Transducer Replacement	SK208-150	2/21/05	No Effect
CAB05-4	Flap Actuator Support Bracket Inspection/Replacement	SK208-158	4/4/05	No Effect
CAB05-5	Pilot's Operating Handbook Temporary Revision and Supplement S1 Revisions	None	3/14/05	No Effect
CAB05-6	ALTAIR ADAS+ Annunciator Installation and Configuration File Modification	None	3/14/05	No Effect
CAB05-7	Engine Shroud Segment Inspection	None	5/2/05	No Effect
CAB05-8	Pilot's Operating Handbook Temporary Revision and Supplement S1 Revision	None	7/25/05	No Effect
CAB05-9	Engine Oil Tank Filler Cap Inspection	None	6/27/05	No Effect
CAB05-10	Altair ADAS+ Processor Software Modification	None	9/5/05	No Effect
CAB05-11	R134A Air Conditioner System Installation	SK208-157	1/18/11	No Effect
CAB05-12	Flashing Beacon Installation Inspection/Modification	None	10/31/05	No Effect
CAB05-13	Right Inboard Flap Bell Crank Bearings Inspection	None	10/31/05	No Effect
CAB05-14	Pilot's Operating Handbook Supplement S1 Revision	None	12/12/05	No Effect
CAB05-15	300 Ampere Starter-Generator Installation	SK208-165	3/22/11	----
CAB05-16	Nose Landing Gear Lord Shimmy Dampener Installation	SK208-164	12/12/05	No Effect
CAB05-17	Main Landing Gear Trunnion and Fairing Inspection	None	12/12/05	No Effect
CAB05-18	Engine Fuel Pump Coupling Inspection	None	12/23/05	No Effect
CAB06-1	Pilot's Operating Handbook Supplement S1 Revision	None	1/9/06	No Effect
CAB06-2	Rudder Torque Tube Inspection	SK208-149 SK208-99	3/20/06	No Effect
CAB06-3	Control Quadrant Modification	SK208-166	3/20/06	No Effect
CAB06-4	Engine Compressor Vane Ring Damping Strap Inspection	None	5/15/06	No Effect
CAB06-5	Honeywell KS270C Pitch Servo and KS271C Roll Servo Tach Generator Modification	None	5/1/06	No Effect
CAB06-6	Additional Beverage Cup Holder Installation	SK208-168	5/1/06	No Effect
CAB06-7	Cargo Pod Main Landing Gear Opening Modification	SK208-167	8/21/06	No Effect
CAB06-8	Pilot's Operating Handbook Supplement S1 Revision and Operational Limitation Placards Installation	None	9/18/06	No Effect
CAB06-9	Rudder Spar Inspection	None	10/2/06	No Effect
CAB06-10	Electrical Ground Strap Inspection	None	10/2/06	No Effect
CAB06-11	Flight into Known Icing - Low Airspeed Awareness System Installation	SK208-171	2/19/07	----
CAB06-12	Engine Fire Detector Cable Inspection	None	12/26/06	No Effect
CAB07-1	Nose Landing Gear Over Travel Indicator/LORD Shimmy Dampener Installation	None	2/19/07	6/1/16
CAB07-2	Engine Primary Exhaust Duct Inspection	None	2/19/07	No Effect

CAB07-3	Pilot's Operating Handbook Supplement S1 Revision and Operational Limitation Placard Installation	None	3/5/07	No Effect
CAB07-4	12 Volt Direct Current Power Outlets Installation	SK208-169	4/2/07	----
CAB07-5	Pilot's Operating Handbook Revision	None	6/25/07	No Effect
CAB07-6	Fuel Capacity Placard Replacement	None	6/25/07	No Effect
CAB07-7	Engine Spark Igniters Inspection	None	9/18/07	No Effect
CAB08-1	Fuel Control Unit Rod End Hardware Replacement	None	1/21/08	No Effect
CAB08-2	Wing Electrical Wiring Harness Inspection	None	2/4/08	No Effect
CAB08-3	Windshield Anti-Ice Panel Seal Modification	SK208-173	2/4/08	No Effect
CAB08-4	Alternate Static Source Selector Valve Inspection	None	10/6/08	No Effect
CAB08-5	Pilot's Abbreviated Checklist Revision	None	5/12/08	No Effect
CAB08-6	Aileron Control Cable Attachment to Quadrant Modification	None	10/27/08	4/1/10
CAB08-7	Low Airspeed Awareness System Installation	SK208-175D	10/19/09	12/1/12
CAB08-8	Stall Warning Margin Adjustment/Reset	None	12/15/08	No Effect
CAB08-9	Garmin GFC-700 Autopilot Roll and Yaw Servos Bridle Cable Clamps Inspection	None	11/24/08	4/1/10
CAB09-1	Engine Inlet Inertial Separator Drain Hole Inspection	None	5/11/09	No Effect
CAB09-2	Elevator Pushrod Placards Installation	None	5/11/09	No Effect
CAB09-3	Line and Tube Assemblies Inspection	None	6/8/09	No Effect
CAB09-4	Aft Wing Spar Attach Bolt Retaining Nut Torque	None	11/16/09	4/1/10
CAB09-5	Engine Compressor Turbine Blades Replacement	None	6/22/09	No Effect
CAB09-6	Garmin G1000 System Software Upgrade to Version 767.04	None	8/24/09	No Effect
CAB09-7	Garmin G1000 Synthetic Vision Installation	None	8/24/09	4/1/10
CAB09-8	ACU Wiring Modification for STBY PWR INOP CAS Message	None	6/22/09	No Effect
CAB09-9	TKS Ice Protection System Installation	SK208-174D	10/19/09	No Effect
CAB09-10	Generator Field Circuit Breaker Inspection	None	10/19/09	No Effect
CAB09-11	Garmin G1000 Avionics ChartView Option	None	10/20/09	No Effect
CAB10-1	Pratt & Whitney Engine Services ADAS+ ETM Torque Transducer Replacement and Software Update	None	3/15/10	No Effect
CAB10-2	Instrument Panel Control Column Cutout Modification	None	4/12/10	No Effect
CAB10-3	Wing Aileron Cable and Pulley Inspection	None	5/18/10	No Effect
CAB10-4	Pratt & Whitney ADASd Software Upgrade	None	5/18/10	No Effect
CAB10-5	Flap Pushrod Rod End Inspection	None	7/20/10	No Effect
CAB10-6	Right Inboard Flap Bell Crank Bearing Inspection/Replacement	None	7/20/10	No Effect
CAB10-7	Elevator Hinge Bracket Inspection	None	7/20/10	No Effect
CAB10-8	NAV/Strobe Light Replacement	None	7/20/10	No Effect
CAB10-9	Roll Servo Fairlead Cover Installation	None	9/17/10	No Effect

CAB10-10	Horizontal Stabilizer Shim Inspection	None	10/27/10	No Effect
CAB11-1	P3 and Py Tube Inspection	None	2/15/11	No Effect
CAB11-2	Oil Pressure Transducer and Connector Inspection	None	2/15/11	No Effect
CAB11-3	Garmin G1000 System Software Upgrade to Version 0767.07	None	4/26/11	No Effect
CAB11-4	Garmin GWX 68 Weather Radar Modification	None	5/24/11	No Effect
CAB11-5	New 208/208B Task-Based Inspection Program	None	5/16/14	No Effect
CAB11-6	Oil Scavenge Hose Inspection	None	8/23/11	No Effect
CAB11-7	Engine Mount Inspection for Sufficient Paint Coverage	None	9/13/11	No Effect
CAB11-8	Garmin GFC-700 Autopilot Roll and Yaw Servos Bridle Cable Clamps Inspection	None	11/4/11	No Effect
CAB-21-01	Cabin Heat Bleed Air Flow Restrictor Modification	None	10/10/13	6/1/15
CAB-24-01	Circuit Breaker Panel Modification	None	9/18/13	No Effect
CAB-25-01	Cargo Barrier Modification	None	10/18/13	No Effect
CAB-25-02	Field Interior Installation	None	4/24/15	No Effect
CAB-27-01	Rudder Trim Inspection	None	02/09/15	No Effect
CAB-28-01	Fuel Vent Line Inspection	None	07/14/15	No Effect
CAB-30-01	TKS Fill Cap Placard Replacement	None	4/23/12	No Effect
CAB-30-02	FIKI Installation for Airplanes with Provisions	None	5/17/13	No Effect
CAB-30-03	TKS Fill Cap Placard Replacement	None	9/10/14	No Effect
CAB-30-05	Single Filter Element for TKS Aircraft	None	3/3/15	No Effect
CAB-30-06	FIKI Installation for Airplanes with a Fairing and with Provisions	None	1/7/14	No Effect
CAB-30-07	TKS Ice Warning Placard Replacement	None	9/10/14	No Effect
CAB-31-01	CVDR Installation	None	10/21/15	No Effect
CAB-32-01	Brake System Modification and Cleansing Procedure	None	3/14/14	No Effect
CAB-32-02	NLG Spring Forward Support Assembly Modification	None	11/5/14	9/1/14
CAB-32-03	Brake System Modification	None	4/17/14	No Effect
CAB-34-01	Garmin G1000 Enhanced Search and Rescue Enablement Option	None	5/10/12	No Effect
CAB-34-02	Garmin G1000 System Software Upgrade to Version 0767.13	None	5/15/12	No Effect
CAB-53-01	208 Bulkhead Fastener Inspection at FS 165.45	None	9/22/14	No Effect
CAB-55-01	Inspection/Modification Of Gap Between Vertical Forward Spar Caps and Canted Bulkhead	None	9/9/15	No Effect
CAB-57-01	Right Wing Repair	None	8/15/12	No Effect
CAB-57-02	Spar Fitting and Attach Bracket Inspection	None	2/3/15	No Effect
CAB-71-01	Cowl Lock Modification	None	8/7/13	No Effect
CAB-71-02	Engine Truss Inspection at Fuel Ecology Tank Bracket and Induction Plenum	None	9/18/14	No Effect

CAB-77-01	Fast Engine Trend Monitoring Installation for Airplanes with Provisions	None	6/9/14	No Effect
CAB-80-01	300 Ampere Starter/Generator Installation for 208B EX (867 SHP) Airplanes	None	10/27/14	No Effect

Table 2. Service Kit List

Service Kit Number	Title	Service Bulletin Number	Service Bulletin Date	Manual Incorporation
SK208-1	Oil Breather Line Improvement	CAB85-6	9/13/85	No Effect
SK208-2	Pilot and Copilot Seat Locking Pin	CAB85-2	8/9/85	3/1/99
SK208-3	Volt/Ammeter Switch Replacement	CAB85-11	11/8/85	No Effect
SK208-4	Improved Courtesy Light Installation	SSP85-9	12/1/85	No Effect
SK208-5	Optional RH Panel Improvement	SSP85-13	12/20/85	No Effect
SK208-6	Circuit Breaker Panel Connector - Jackscrew Replacement	CAB85-12	11/8/85	No Effect
SK208-7	Inertial Separator Linkage Support Bracket Replacement	CAB85-14	12/6/85	No Effect
SK208-8	Fuel Quantity Indicating System Improvements	CAB85-9	11/1/85	No Effect
SK208-9	Flight Hour Recorder System Modification	CAB85-17	12/20/85	3/1/99
SK208-10	Cargo Pod Water Drains Installation	CAB86-27	6/19/87	3/1/99
SK208-11	Electrical Bonding Ground Strap Installation	CAB86-21	7/25/86	3/1/99
SK208-12	Maximum Takeoff Weight Increase Modification	CAB85-13	11/15/85	3/1/99
SK208-13	208 Extended Vertical Tail Installation	CAB85-13	11/15/85	3/1/99
SK208-14	Fin/Rudder Hinge Bracket	CAB85-13	11/15/85	3/1/99
SK208-15	LH Instrument Panel Modification	SSP86-4	10/24/86	No Effect
SK208-16	Torque Indicator Installation Improvement	CAB85-16	12/13/85	3/1/99
SK208-17	Improved Drive For Standby Alternator	CAB86-18 R1	12/7/90	3/1/99
SK208-18	Fuel Shutoff Valve Screw Replacement	CAB86-3	4/11/86	No Effect
SK208-19	Cowl Door Latch Pin Modification	CAB86-10	4/25/86	3/1/99
SK208-20	Fuel Selector Off Warning System Installation	CAB86-8	10/10/86	3/1/99
SK208-21	Nose/Main Landing Gear Wheel and Bearing Improvements	CAB88-2	3/4/88	No Effect
SK208-22	Inertial Separator and Induction Air Plenum Modification	CAB87-12	9/18/87	No Effect
SK208-23	Improved Secondary Exhaust System	CAB86-32 R1	12/21/90	3/1/99
SK208-24	External Start Contactor Suppressor	CAB86-24	8/29/86	3/1/99
SK208-25	Fuel Reservoir and Flapper Valve Modification	CAB87-13	10/16/87	3/1/99
SK208-26	Low Fuel Level Transmitter Nut Retention	CAB86-26	9/5/86	No Effect
SK208-27	Fuselage Sealing Procedures	CAB86-25	9/5/86	No Effect
SK208-28	Cancelled	----	----	----
SK208-29	Improved Door Restraint Installation	CAB88-16	4/15/88	3/1/99
SK208-30	Control Column Aileron Cable Guard Improvement	CAB88-5	3/18/88	No Effect

SK208-31	Cancelled	----	----	----
SK208-32	Circuit Breaker Panel Cover Installation	CAB88-26	7/29/88	3/1/99
SK208-33	Circuit Breaker Panel Cover Installation	CAB88-26	7/29/88	3/1/99
SK208-34	Circuit Breaker Panel Cover Installation	CAB88-26	7/29/88	3/1/99
SK208-35	Inertial Separator/Induction Air Plenum Modification	CAB87-12	9/18/87	No Effect
SK208-36	Outboard Wing Fuel Drain Valve Installation	CAB88-6	3/18/88	3/1/99
SK208-37	Cargo Barrier Attachment Improvement	CAB88-18	5/6/88	3/1/99
SK208-38	Elevator Trim Chain Cover Assembly	CAB88-7	3/18/88	No Effect
SK208-39	Ground Wire For Windshield Anti-Ice Panel	CAB87-5	4/24/87	3/1/99
SK208-40	Large Oil Cooler Installation	CAB87-17	4/23/93	3/1/99
SK208-41	Crew Step Structural Improvements	CAB89-14	6/2/89	----
SK208-42	Radio Cover Watershield Installation and Cabin Top Sealing	CAB88-8	3/18/88	3/1/99
SK208-43	Cowl Scupper and Drain Installation	CAB88-41	12/9/88	3/1/99
SK208-44	Crew Step Structural Improvements	CAB89-14	6/02/89	3/1/99
SK208-45	Inertial Vane Separator Vane Improvements	CAB88-15	4/8/88	3/1/99
SK208-46	Partition Net Placard	CAB88-25	7/29/88	3/1/99
SK208-47	Cowl Door Rub Strips	CAB88-17	4/22/88	No Effect
SK208-48	Tow Limit Modification	CAB88-9	3/18/88	3/1/99
SK208-49	Pitot Static System Line Replacement	CAB88-36	11/18/88	3/1/99
SK208-50	Flap System Adjustable Interconnect Rod	CAB88-13	3/25/88	No Effect
SK208-51	Nose Gear Torque Link Replacement	CAB89-2 R2	7/6/90	3/1/99
SK208-52	Wing Tank External Sump Installation	CAB88-23	7/29/88	3/1/99
SK208-53	Cancelled	----	----	----
SK208-54	Static Source Selector Valve Modification	CAB88-34	11/11/88	No Effect
SK208-55	Exhaust Hanger Modification (Cargo Pod or Floats)	CAB88-20	5/31/88	3/1/99
SK208-56	Cancelled	----	----	----
SK208-57	Fuel Pump Unit Drain Reservoir Installation	CAB89-16	6/9/89	3/1/99
SK208-58	Pointer 3000-1 ELT Installation	CAB89-4	1/13/89	No Effect
SK208-59	Nose Gear Steering Bushing Replacement	CAB88-40	12/9/88	No Effect
SK208-60	208 Utility Seat Frame Padding Installation for One Seat	CAB89-11	5/19/89	No Effect
SK208-61	208 Turbine Oil Hose Assembly Replacements	CAB89-1	1/6/89	3/1/99
SK208-62	208 Door Lock Pin Replacements	CAB89-3	1/13/89	No Effect
SK208-63	208 Wing Skin Stiffener Installation	CAB88-32	10/14/88	No Effect
SK208-64	Bleed Air Pressure Relief Valve Installation for Aircraft Without Surface Deice	CAB89-26 R1	9/8/89	3/1/99
SK208-65	Bleed Air Pressure Relief Valve Installation for Aircraft Without Surface Deice	CAB89-26 R1	9/8/89	3/1/99
SK208-66	Air Conditioner Compressor Bracket Replacement	CAB89-19	7/14/89	3/1/99

SK208-67	Nose Gear Fork Replacement - Extended Fork	None	6/20/89	3/1/99
SK208-68	Nose Gear Fork Replacement - Standard Fork	None	6/20/89	3/1/99
SK208-69	Enlarged Cargo Pod Heat Shield Installation	CAB89-30	11/3/89	6/1/11
SK208-70	Airborne Bleed Air Valves Retrofit Kit	CAB90-9 R1	3/23/90	3/1/99
SK208-71	Inboard Flap Roller and Track Removal	CAB89-31	11/24/89	3/1/99
SK208-72	Upper Right Flap Bellcrank Support Replacement	CAB89-32 R2	7/2/92	3/1/99
SK208-73	Cancelled	----	----	----
SK208-74	Nose Gear Fork Tow Point	CAB90-5	3/2/90	3/1/99
SK208-75	Bulkhead Control Cable Cutout Modification and Floorboard Reinforcement	CAB90-21 R2	6/21/91	----
SK208-76	Bulkhead Control Cable Cutout Modification and Floorboard Reinforcement	CAB90-21 R2	6/21/91	----
SK208-77	Cancelled	----	----	----
SK208-78	Air Conditioner Condenser Cowl Seal Replacement	CAB91-12	4/26/91	3/1/98
SK208-79	Improved Airspeed Warning Switch Installation	CAB90-32	12/07/90	3/1/98
SK208-80	675 SHP PT6A-114A Engine Installation	SNL90-7	10/12/90	3/1/98
SK208-81	Door Handle Plunger Replacement	CAB91-24	8/2/91	----
SK208-82	Heater Valve Improvement	CAB91-26	8/30/91	3/1/98
SK208-83	Control Column Bearings and Aileron Cable Guard Replacements	CAB91-27	9/20/91	3/1/98
SK208-84	600 SHP PT6A-114 Engine Installation	SNL90-8	9/24/93	3/1/98
SK208-85	208A to 208 Cargomaster Conversion	None	11/06/90	----
SK208-86	Conversion of US 208 to Brazilian 208	None	11/06/90	No Effect
SK208-87	208 Cargo to Passenger Conversion	None	5/31/91	No Effect
SK208-88	Upper Rudder Hinge Bracket/Skin Reinforcement	CAB92-2	1/17/92	3/1/98
SK208-90B	Firewall Fitting Reinforcement Installation	CAB91-9 R2	7/2/92	3/1/98
SK208-91	Cancelled	----	----	----
SK208-92	Flap Support Modification Installation	CAB92-16 R3	8/28/92	3/1/98
SK208-93	Cancelled	----	----	----
SK208-94	Engine Power Control Cable Replacement	CAB91-34	11/22/91	3/1/98
SK208-95	Engine Fuel Control Lever Replacement	CAB91-22	7/5/91	3/1/98
SK208-96	Cancelled	----	----	----
SK208-97	Floorboard Reinforcement Installation	CAB93-3	3/12/93	No Effect
SK208-98	Flap Bellcrank Connecting Rod Clearance Modification	CAB92-15	7/24/92	No Effect
SK208-99	Lower Rudder Hinge Replacement	CAB92-18 R1 CAB06-2	10/16/92 3/20/06	3/1/98
SK208-100	Control Cable Clearance Modification	No Longer Available	----	No Effect
SK208-101	Upper and Lower Crew Door Hinge Attach Repair	CAB93-5	4/30/93	3/1/99
SK208-102	Left Elevator Hinge Replacement	CAB93-12	6/30/95	3/1/99

SK208-103	Floorboard Reinforcement Installation	CAB93-3	3/12/93	No Effect
SK208-104	Upper and Center Rudder Hinge Bracket Modification	CAB93-6	4/9/93	3/1/99
SK208-105	Upper and Center Vertical Fin Rudder Hinge Replacement	CAB93-6	4/9/93	3/1/99
SK208-106	Right Elevator Hinge Replacement	CAB93-12	6/30/95	3/1/99
SK208-107	Elevator Center Pivot Arm Hinge Replacement	CAB93-12	8/27/93	3/1/99
SK208-108	Propeller Control Cable Replacement	CAB93-4	4/30/93	3/1/99
SK208-109	Flap Outboard Support Inspection and Modification	CAB93-11	8/27/93	No Effect
SK208-110	Low Fuel Level Switch Cover Replacement	CAB92-19	10/23/92	3/1/99
SK208-111	Throttle Control Quadrant Cover Doubler Installation	CAB93-9	7/23/93	3/1/99
SK208-112	Bleed Air System Pressure Relief Valve Installation	CAB93-2	3/12/93	3/1/99
SK208-113	Windshield Anti-Ice Panel Upper Retention Modification	CAB93-21	11/19/93	8/1/95
SK208-114	Cancelled	----	----	----
SK208-115	Oxygen Control Lever Modification	CAB93-19	10/22/93	8/1/95
SK208-116	Aileron Hinge Bolt Change	CAB93-18	10/8/93	3/1/08
SK208-117	Crew Seat Vertical Adjust Bearing Inspection/Replacement	CAB95-6	5/26/95	No Effect
SK208-118	Elevator Trim Chain Cover Installation	CAB94-9	3/25/94	8/1/95
SK208-119	Flap Switch Guard Installation/Modification	CA894-16	10/28/94	8/1/95
SK208-120	Cancelled	----	----	----
SK208-121	Fuel Reservoir Structure Modification	CAB98-17	11/30/98	No Effect
SK208-122	Standby Alternator Drive Pulley With Drain and Oil Collection Can	CAB96-23	12/16/96	5/1/96
SK208-123	Flap Bellcrank Attach Bolt Replacement	CAB95-11 R1	6/30/95	8/1/95
SK208-125	Ignitor Lead Cable Routing Modification	CAB96-11	3/1/96	No Effect
SK208-127	Electrical Isolation of Pilot and Copilot Press to Talk Switches	CAB97-11 R1	10/27/97	----
SK208-128	Avionics Cooling Fan Replacement	CAB96-10	2/9/96	No Effect
SK208-129	Engine Secondary Exhaust Duct Hanger Modification and Cowling Inspection	CAB00-8	5/29/00	11/3/03
SK208-130	Avionics Number Two Power Switch/Breaker Replacement	CAB97-8	6/30/97	No Effect
SK208-133	Passenger Door Step Support Modification	CAB98-2	2/23/98	----
SK208-134	Main Landing Gear Lower Fairing Baffle Replacement	CAB98-6	3/23/98	----
SK208-136	Right Brake Master Cylinder Supply Hose Modification	CAB208-136	5/4/98	----
SK208-138	Pilot and Copilot Seat Rails and Floor Structure Modification	CAB00-12	10/30/00	No Effect
SK208-139A	Engine Secondary Exhaust Duct Hanger Modification	CAB00-9	5/29/00	11/3/03
SK208-140	Rudder Bar Assembly Modification and Barrel Nut Replacement	CAB00-5	4/17/00	----
SK208-141	Secondary Exhaust Duct Installation	----	8/18/00	11/3/03

SK208-142	Emergency Power Lever Shear Wire Installation	CAB01-15	12/17/01	12/17/01
SK208-145	Plywood Floorboard Installation - 5/8 Inch	CAB02-3	2/25/02	11/3/03
SK208-146	Ice Protection Installation/Modification	CAB04-9	10/4/04	----
SK208-147	Engine Oil Pressure/Oil Temperature Indicator Installation	CAB03-2	2/24/03	----
SK208-148A	Flap System Inboard Forward Bellcrank Installation	CAB02-12	1/27/03	11/3/03
SK208-149	Rudder Torque Tube Replacement	CAB06-2	3/20/06	No Effect
SK208-150	Torque Transducer Replacement	CAB05-3	2/21/05	----
SK208-156	Air Conditioning Conversion From R12 to R134A Refrigerant	CAB04-12	11/1/04	----
SK208-157	R134A Air Conditioner System Installation	CAB05-11	1/18/11	----
SK208-158	Flap Actuator Support Bracket Inspection/Replacement	CAB05-4	4/4/05	No Effect
SK208-159	Security Lock Installation	CAB04-5	6/14/04	----
SK208-163	ARTEX Three Frequency Emergency Locator Transmitter (ELT) Installation	CAB05-2	1/24/05	----
SK208-164	Nose Landing Gear Lord Shimmy Dampener Installation	CAB05-16	12/12/05	----
SK208-165	300 Ampere Starter-Generator Installation	CAB05-15	3/22/11	----
SK208-166	Control Quadrant Modification	CAB06-3	3/20/06	----
SK208-167	Cargo Pod Main Landing Gear Opening Modification	CAB06-7	8/21/06	No Effect
SK208-168	Additional Beverage Cup Holder Installation	CAB06-6	5/1/06	No Effect
SK208-169	12 Volt Direct Current Power Outlets Installation	CAB07-4	4/2/07	----
SK208-171	Flight into Known Icing - Low Airspeed Awareness System Installation	CAB06-11	2/19/07	----
SK208-173	Windshield Anti-Ice Panel Seal Modification	CAB08-3	2/4/08	----
SK208-174D	TKS Ice Protection System Installation	CAB09-9	10/19/09	----
SK208-175D	Low Airspeed Awareness System Installation	CAB08-7	10/19/09	12/1/12